



**IEC 60598-2-8, Edition 2 (1996) – A1 (2000) A2 (2007)**  
**TESTING AND MEASURING EQUIPMENT/ALLOWED SUBCONTRACTING**  
**Luminaires – Part 2 – Particular requirements**  
**Section 8: Handlamps**

**R** = Required by Lab

**S** = May be subcontracted

**W** = Witness testing

**3PPS** = Three Phase Power Supply required

<b>Clause</b>	<b>Measurement/testing</b>	<b>Testing / measuring equipment / material needed</b>	<b>Subcontracting</b>
8.6.6.1	<i>Pull test on grid or guard, sealed handlamps</i>	<i>Pull test device, torque test device</i>	<b>R</b>
8.6.6.2	<i>Impact tests</i>	<i>Impact test apparatus (fig. 1)</i>	<b>R</b>
8.10.4.1	<i>Flexing test</i>	<i>Apparatus for flexing test (fig. 2)</i>	<b>R</b>
8.12.1	<i>Endurance and thermal tests</i>	<i>Heating cabinet (minimum 70°C)</i>	<b>R</b>
8.15.1	<i>Pressure test</i>	<i>Crush-test apparatus (fig. 3) / Heating cabinet (minimum 100°C)</i>	<b>R</b>