



## IEC 61347-2-2/2000 - Am1/2005 - Am2/2006

### **TESTING AND MEASURING EQUIPMENT/ALLOWED SUBCONTRACTING** **Lamp controlgear – Part 2-2: Particular requirements for d.c. or a.c. supplied** **electronic step-down convertors for filament lamps**

*R=Required by Lab.*

*S=May be subcontracted*

*W=Witness testing*

*3PPS=Three Phase Power Supply required*

<b>Clause</b>	<b>Measurement/testing</b>	<b>Testing / measuring equipment / material needed</b>	<b>Subcontracting</b>
15 – 1.6 – 1.7	Heating test	Hybrid Recorder (temperature rise equipment; Resistance meter; Voltmeter; Resistive loads; Current based loads)	<b>R</b>
1.6.3.3	Vibration test	Appropriate vibration equipment	<b>S</b>