



TESTING AND MEASURING EQUIPMENT/ALLOWED SUBCONTRACTING

IEC PAS 62722-1:2011

Luminaire performance – Part 1: General requirements

“R”	Required
“S”	May be subcontracted, see OD 2012
“SF”	Specialized Facility, see IECEE 02-2
“W”	Witness testing in the categories “MED” and “MEAS”
“3PPS”	Three Phase Power Supply required

Clause	Measurement/testing	Testing / measuring equipment / material needed	Subcontracting
6	Photometric data – LOR	Integrating Sphere or Goniophotometer (with measuring system, calibrated lamps source)	R
	Photometric data – Distribution of luminous intensity	Goniophotometer (with measuring system, calibrated lamps source)	R
		Stabilized supply voltage, voltage meter	R
7	Electrical data	Stabilized supply voltage, watt meter, voltage meter, ampere meter	R
8	Luminaire efficacy data	Nothing Special	--
9	Environmental data	Nothing special	--