



## IEC 61010-2-040 - Edition 1 TESTING AND MEASURING EQUIPMENT/ALLOWED SUBCONTRACTING

R=Required by Lab

S=May be subcontracted

W = May be witnessed, equipment not necessary in CBTL

Clause	Measurement/testing	Testing / measuring equipment / material needed	Subcontracting
7.4.101	transfer of loads into and out of the chamber	force gauge (250 N)	R
7.101	doors, conveyors, etc.	force gauge (150 N)	R
7.105	chamber pressure	air pressure indicator (0.2 bar, 20 kPa)	R
11.102	Illumination level	suitable illumination meter	S
13.1	poisonous and injurious gases	suitable gas meter	S
13.101	Toxic sterilants	Suitable gas meter	S

Note: The presence of equipment alone does not indicate a satisfactory situation. Assessors must evaluate the equipment design, calibration, uncertainty and documentation to ensure compliance with the directions of the standard. The requirements of ISO/IEC 17025 regarding validation are applicable, as the tests of this standard are not standardised tests.