



TESTING AND MEASURING EQUIPMENT/ALLOWED SUBCONTRACTING

Safety of hand-held motor-operated electric tools – Band saws

IEC 60745-2-20 1st . Edition (2003) + A1 (2008)

R = Required by Lab

S = May be subcontracted

W = Witness testing

3PPS = Three Phase Power Supply required

Clause	Measurement/testing	Testing / measuring equipment / material needed	Subcontracting
12	Heating	Brake	R

Note: The presence of equipment alone does not indicate a satisfactory situation. Assessors must evaluate the equipment design, calibration, uncertainty and documentation to ensure compliance with the directions of the standard.. The requirements of ISO/IEC 17025 regarding validation are applicable, as the tests of this standard are not standardized tests.