



**TESTING AND MEASURING EQUIPMENT/ALLOWED SUBCONTRACTING**  
**IEC 61558-2-5, 2 Edition (2010)**

**Safety of transformers, reactors, power supply units and combinations thereof – Part 2-5: Particular requirements and tests for transformers for shavers, power supply units for shavers and shaver supply units**

- “R” Required
- “S” May be subcontracted, see OD 2012
- “SF” Specialized Facility, see IECEE 02-2
- “W” Witness testing in the categories “MED” and “MEAS”
- “3PPS” Three Phase Power Supply required

Clause	Measurement/testing	Testing / measuring equipment / material needed	Subcontracting
16.101.1	Pendulum hammer test	Apparatus for mechanical strength test	R