



**TESTING AND MEASURING EQUIPMENT/ALLOWED SUBCONTRACTING
IEC 61347-2-2 Edition 2 2011**

**Lamp controlgear – Part 2-2: Particular requirements for d.c. or a.c. supplied
electronic step-down convertors for filament lamps**

- “R” Required
- “S” May be subcontracted, see OD 2012
- “SF” Specialized Facility, see IECEE 02-2
- “W” Witness testing in the categories “MED” and “MEAS”
- “3PPS” Three Phase Power Supply required

Clause	Measurement/testing	Testing / measuring equipment / material needed	Subcontracting
15	Transformer heating	Hybrid Recorder (temperature rise equipment; Resistance meter; Voltmeter; Resistive loads; Current based loads)	R
Annex I	Vibration test	Appropriate vibration equipment	S