



TESTING AND MEASURING EQUIPMENT/ALLOWED SUBCONTRACTING

IEC 61000-3-2: 2005- A1: 2008 – A2: 2009

R = Required by Lab

S = May be subcontracted

W = Witness testing

3PPS = Three Phase Power Supply required

Clause	Measurement/testing	Testing/ measuring equipment / material needed	Subcontracting
6.2	Measurement of harmonics	Power source , harmonic meter	R

Note: The presence of equipment alone does not indicate a satisfactory situation. Assessors must evaluate the equipment design, calibration, uncertainty and documentation to ensure compliance with the directions of the standard. The requirements of ISO IEC 17025 regarding validation are applicable, as the tests of this standard are not standardised tests