



IEC 60598-2-17, Edition 1 (1984) – A1 (1987) – A2 (1990)
TESTING AND MEASURING EQUIPMENT/ALLOWED SUBCONTRACTING
Luminaires – Part 2 – Particular requirements
Section 17: Luminaires for stage lighting, television, film and photographic studios (outdoor and indoor)

R = Required by Lab

S = May be subcontracted

W = Witness testing

3PPS = Three Phase Power Supply required

Clause	Measurement/testing	Testing / measuring equipment / material needed	Subcontracting
17.6.3	Lamp explosion test	Wooden base / Five layers of cotton gauze	R
17.6.4	Test on the hanger (stirrup)	Load devices	R