



IEC 61347-2-11: 2001
TESTING AND MEASURING EQUIPMENT/ALLOWED SUBCONTRACTING
Lamp controlgear – Part 2-11: Particular requirements for
miscellaneous electronic circuits used with luminaires

R=Required by Lab
S=May be subcontracted

Clause	Measurement/testing	Testing / measuring equipment / material needed	Subcontracting
ALL	-	NOTHING SPECIAL	-

Note: The presence of equipment alone does not indicate a satisfactory situation. Assessors must evaluate the equipment design, calibration, uncertainty and documentation to ensure compliance with the directions of the standard. The requirements of ISO Guide 25 regarding validation are applicable, as the tests of this standard are not standardised tests.