



IEC 60601-2-21 Edition (1994) + Am.1: 1996
TESTING AND MEASURING EQUIPMENT/ALLOWED SUBCONTRACTING

R=Required by Lab

S=May be subcontracted

Clause	Measurement/testing	Testing / measuring equipment / material needed	Subcontracting
33	Infra-red radiation	- Suitable infrared irradiance level meter	S
43.103	Fire prevention	- Suitable oxygen concentration meter	R
		- Air flow rate meter	R
50	Accuracy of operating data	- Skin temperature sensor	R
		- Water bath	R
102	Sound pressure level	- Sound level meter according to IEC 60651	R
103	Concentration of carbon dioxide	- Suitable carbon dioxide concentration meter	R

Note: The presence of equipment alone does not indicate a satisfactory situation. Assessors must evaluate the equipment design, calibration, uncertainty and documentation to ensure compliance with the directions of the standard. The requirements of ISO Guide 25 regarding validation are applicable, as the tests of this standard are not standardised tests.