



**IEC SYSTEM FOR CONFIRMITY
TESTING AND CERTIFICATION
OF ELECTRICAL EQUIPMENT**

COMMITTEE OF TESTING LABORATORIES

IEC 61558-2-4, ED. 2 (2009)

TESTING AND MEASURING EQUIPMENT/ALLOWED SUBCONTRACTING

**Safety of transformers, reactors, power supply units and similar products for
supply voltages up to 1100 V**

**Part 2-4: Particular requirements and tests for isolating transformers and
power supply units incorporating isolating transformers**

R=Required by Lab.

S=May be subcontracted

W=Witness testing

3PPS=Three Phase Power Supply required

| <i>Clause</i> | <i>Measurement/testing</i> | <i>Testing / measuring equipment / material needed</i> | <i>Subcontracting</i> |
|---------------|----------------------------|--|-----------------------|
| | | NOTHING SPECIAL | |