



**TESTING AND MEASURING EQUIPMENT/ALLOWED SUBCONTRACTING
IEC 61000-4-4: 2012, Edition 3.0
Electromagnetic compatibility (EMC)
Part 4-4: Testing and measurement technique
Electrical fast transient/burst immunity test**

- “R” Required
- “S” May be subcontracted, see OD 2012
- “SF” Specialized Facility, see IECEE 02-2
- “W” Witness testing in the categories “MED” and “MEAS”
- “3PPS” Three Phase Power Supply required

Clause	Measurement/testing	Testing / measuring equipment / material needed	Subcontracting
8	<i>Immunity test to Fast transients</i>	<i>Burst Generator, Coupling/Decoupling Network, Capacitive Clamp, 33 nF capacitor for direct injection, RGP, Interconnection Cable (for Clamp to Generator)</i>	R