



**TESTING AND MEASURING EQUIPMENT/ALLOWED SUBCONTRACTING
IEC 61000-3-3 : 1994 + A1 : 2001 + A2 : 2005**

- “R” Required
- “S” May be subcontracted, see OD 2012
- “SF” Specialized Facility, see IECEE 02-2
- “W” Witness testing in the categories “MED” and “MEAS”
- “3PPS” Three Phase Power Supply required

Clause	Measurement/testing	Testing / measuring equipment / material needed	Subcontracting
6	Measurement of flickers and voltage fluctuations	Power supply, Voltage fluctuation meter, Impedance network, flicker meter	R